



DLAŽBA

VZORY POKLÁDEK

ARTE Square kombi





Skladba jedné vrstvy:
 Typ "A" - 40/20/8 cm - 4 ks
 Typ "B1" - 30/20/8 cm - 4 ks
 Typ "B2" - 30/20/8 cm - 4 ks
 Typ "C" - 30/20/8 cm - 4 ks
 Typ "D" - 20/20/8 cm - 4 ks
 Typ "E" - 20/10/8 cm - 4 ks





1 vrstva = 0,96 m²

120/80/8	= 4x A(40/20/8) + 4x B1(30/20/8) + 4x B2(30/20/8) + 4x C(30/20/8) + 4x D(20/20/8) + 4x E(20/10/8)
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²




Vzor 1	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 14x A(40/20/8) + 4x B1(30/20/8) + 4x B2(30/20/8) + 4x C(30/20/8) + 4x D(20/20/8) + 4x E(20/10/8)
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²




Vzor 2	Prodej na vrstvy: 1 vrstva (kombifforma)
	4x A(40/20/8) + 4x B1(30/20/8) + 4x B2(30/20/8) + 4x C(30/20/8) + 4x D(20/20/8) + 4x E(20/10/8)
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²


ARTE Square kombi




0.15



Vzor 3	Prodej na vrstvy: 1 vrstva (kombiforma) = 4x A(40/20/8) + 4x B1(30/20/8) + 4x B2(30/20/8) + 4x C(30/20/8) + 4x D(20/20/8) + 4x E(20/10/8)
Spotřeba ks/m ²	1 vrstva (kombiforma) = 0,96 m ²



0.15



Vzor 4	Prodej na vrstvy: 1 vrstva (kombiforma) = 4x A(40/20/8) + 4x B1(30/20/8) + 4x B2(30/20/8) + 4x C(30/20/8) + 4x D(20/20/8) + 4x E(20/10/8)
Spotřeba ks/m ²	1 vrstva (kombiforma) = 0,96 m ²